

TABLE OF CONTENTS

<u>Item</u>	<u>Page</u>
<u>NARRATIVE</u>	
<u>SUMMARY AND CONCLUSIONS</u>	2
<u>INTRODUCTION</u>	3
Statement of Problem	3
Project Location	3
Scope of Work	4
<u>PROJECT PARTNERS</u>	5
<u>INVESTIGATIONS</u>	6
Available References	6
Current Investigations	7
<u>PROJECT TIMELINE</u>	8
Highlights	8
Details	9
<u>APPROACH AND FINDINGS</u>	11
Utilization of Previous Investigations	11
Approach for Current Investigations	11
<u>DESIGN DESCRIPTION</u>	12
Mine Pool Discharge Rate	12
Site Considerations	12
Mine Pool Elevation	13
Permanent Solution Description	14
Primary Drain Design	14
Primary Drain Hydraulic Capacity	14
Secondary Drain Design	16
Secondary Drain Hydraulic Capacity	16
Early Warning System Design	16
Continued Mine Pool Elevation Monitoring	17
Mine Pool Response by Discharging at Primary Drain (graph)	18
Bruce Leavitt, PE, PG – Project Review	19
<u>PHOTOS</u>	
"Blowout" and Early Warning System	
Site Investigation and Design Process	
Primary Drain	
Secondary Drain	
<u>SITE PLAN & AS-BUILTS</u>	
Site Plan (1" = 200')	
"As-Builts" (Plan Views & Sections)	
<u>APPENDICES</u>	
<u>APPENDIX A – SITE INFORMATION</u>	
1897 McDonald, PA (artist's rendering) & Site Overview Map (1" = 200')	
<u>APPENDIX B – GEOLOGY AND HYDROGEOLOGY</u>	
Generalized Columnar Section (1" = 10')	
Geologic Cross-Section (Diagrammatic)	
Geologic Drill Hole Logs & Piezometer "As-Builts"	
Overlays – Bed Map, Mine Pool Response Test, Underground Mine Map (1" = 200')	
Water Sample Analyses	
Water Level Monitoring	
<u>APPENDIX C – CONCEPTUAL OPTIONS</u>	
Conceptual Design Options (1" = 100')	
<u>APPENDIX D – COMPUTER DISK</u>	