

## Site Investigation and Design Process



Inspections conducted to determine site conditions. (March 28, 2005)



Piezometers installed as part of hydrogeologic investigation. (March 10, 2005 – photo by Rich Beam, BAMR)



Test pits excavated with pumping conducted to determine favorable locations for Primary and Secondary Drains. (April 8, 2005)



A temporary gravity drain was installed at Test Pit 1 before installation of the permanent Primary Drain. (April 10, 2005)